

BUILDING SAFETY CERTIFICATE

No. 99/2025

Dated:02.09.2025

Certified that the existing building **AL-MAQUAR ENGLISH MEDIUM SCHOOL**(name of the building or premises) at Nadukani, Taliparumba North, Kannur (address) is having block (s)/Floor(s) as per details below

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No of floor(s) in the Block	2					

The building is owned/occupied by **AL-MAQUAR ENGLISH MEDIUM SCHOOL** (name of the institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **LSGD** (Name of Department/Govt.) on 29.08.2025 (date of inspection) in the presence of **The Manager AL-MAQUAR ENGLISH MEDIUM SCHOOL** (name and addresses of the Manager/Secretary or his representative) and that the building /premises is fit for occupancy for running school with effect from 29.08.2025 for a period of One years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.The Certificate is valid for specified time period only
- 2.The safety conditions shall be reviewed and fresh certificate can be obtained beyond the period mentioned
3. The building safety is assessed based on normal weather conditions.

Issued on 29.08.2025 at 2 P.M by

•Strike our whichever is not applicable.

Signature with Seal:

Name:

Designation:

Name & Address of Department /Office :



BIJU P.V

PEN-689613

Asst. Executive Engineer

LID & EW Sub Division

Taliparumba Block District - 1

TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer/Assistant Executive Engineer)

- 1 Name of School : AL-MAQUAR ENGLISH MEDIUM SCHOOL
2 Name of Officer : BUJU P V
3 Location : Nadukani Kannur/ Taliparamba North

4 Period for which the certificate is issued : Up to 31st March 2026

5 Types of building : Permanent RCC Building

	Ground Floor	First Floor
1	6.14x6.40x3.70 m - 7 Nos (Class room)	6.14x6.40x3.70 m - 7 Nos (Class room)

- 6 Nature of defect if any
- a) Foundation and Basement : Nil
b) Superstructure : Nil
c) Doors and Windows : Nil
d) Wood work wrought and put up : Nil
e) Roof : Nil
f) Flooring : Nil
g) Miscellaneous(Cracks if any) : Nil

7 Any Major defects noticed which will render the building unsafe in any manner : No

8 Whether maintenance work have been done properly : Yes, new construction

9 whether the structure is sound or not for conducting classes : Yes, The structure is safe for conducting classes under normal wind and weather condition

The stability of the structure should be examined also with reference to location altitude

1 intensity of wind exposure to flood etc.

2 Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate

Note:

Certified that the School was inspected by me on 29.08.2025 and found to be fit /unfit to conduct classes for the period for the reasons stated above.

Place: Taliparamba
Date: 02.09.2025



Signature

Designation
ASSISTANT EXECUTIVE ENGINEER
LID & EW SUB DIVISION
TALIPARAMBA BLOCK PANCHAYATH.